



Application Guide

UTILITY BOILERS - OIL/GAS FIRED



Furnace Floor

- Normal Service*
- Plicast Tuff Mix
- High Duty Service*
- Plicast KL 3000
- Severe Service*
- Plicast HyMOR 3100 Special
- Plibrico 68S A

Tangent Tube (backup)


- Normal Service*
- Plicast Airlite
- High Duty Service*
- Plicast LWI 20
- Severe Service*
- Plicast Trowl Mix Plus KK
- Plisulate 1900 Block

- ### Burner Throats
- Normal Service*
 - Plibrico 80 AB
 - High Duty Service*
 - Plibrico 68S A
 - Severe Service*
 - Plibrico 85 S Special

- ### Burner Throats (Water Cooled)
- Normal Service*
 - Pligun 3100 Sp
 - High Duty Service*
 - Pligun HyMOR 8
 - Severe Service*
 - Plibrico 85 S Special



Application Note



Heat Recovery Steam Generators (HRSG)

Problem—Deterioration of ceramic fiber insulation between steel liner layers in the exhaust gas stack resulting in shell hot spots.

Solution—Insulation injection repair with:

- Plistix Injectite 2300
- Pligun Verilite (pumped)

F.S. Sperry Co., Inc.

1907 Vanderhorn Drive
Memphis, TN. 38134

Tel: 901-373-9000
Fax: 901-385-3272

www.fssperry.com

This application guide is intended for general information only. Please consult Plibrico Company or your local Plibrico Representative for specific application assistance and product recommendations.