




# Application Guide


## PULVERIZED COAL FIRED CYCLONE BURNERS



Burner Throat

### Burner Throats

- Normal Service*
- Plibrico 60 AB
- High Duty Service*
- Plibrico 80 AB
- Severe Service*
- Plibrico 85S Special



Ignition Arch

### Ignition Arch


- Normal Service*
- Plibrico 60 AB
- Pli-Shot HyMOR 3000
- High Duty Service*
- Plibrico 80 AB
- Pli-Shot HyMOR 3100 Special
- Severe Service*
- Plibrico 85S Special
- Pli-Shot HyMOR 3100

### Slag Tap / Floor

- Normal Service*
- Plibrico 85S Special
- High Duty Service*
- Plibrico SR 90
- Plicast Si-BOND B
- Severe Service*
- Plicast Si-BOND Special



Slag Tap / Floor




Cyclone Burner

### Cyclone Burner

- Normal Service*
- Pligun SiC 80
- Plibrico SR 90
- Severe Service*
- Pli-Shot HyMOR SiC 80
- Plibrico SiC 80

### Application Note Wet Bottom Ash Hopper



Stainless Steel Cricket  
Being Added To Existing  
Wet-Bottom Ash Hopper

- Normal Service*
- Pligun Tuff Mix
- High Duty Service*
- Pligun HyREZIST 2700
- Pligun HyREZIST TS Mix
- Severe Service*
- Pli-Shot HyREZIST 3000
- Plicast HyMOR TSR Plus  
KK



**F.S. Sperry Co., Inc.**  
1907 Vanderhorn Drive  
memphis, TN. 38134

Tel: 901-373-9000  
Fax: 901-385-3272

[www.fssperry.com](http://www.fssperry.com)

This application guide is intended for general information only. Please consult Plibrico Company or your local Plibrico Representative for specific application assistance and product recommendations.